

# Fitness Certificate

To be filled by the Inspecting Officer ( Assistant Engineer )

- 1 Name of the officer - Sri. Vijayan K.  
Sree Saraswathy Vidhyalayam Senior Secondary School,  
Ooruttambalam, Thiruvananthapuram
- 2 Name of School - Three storied RCC Building-L Shaped Main  
Portion- 3x74.60x8.50x3.30m L Shaped  
Portion - 3x18.80x8.20xx3.30 m Portico Portion-  
3x12.85x6.30x3.30m
- 3 Classification of building and size -  
i Permanent (Single or Multi storeyed) - Multi storied  
ii Semi permanent -  
iii Temporary shed -
- 4 Period of which the certificate is issued - 2023-2024
- 5 Nature of defect if any -  
a. Foundation and basement -  
b. Superstructure -  
c. Doors & windows -  
d. Roof -  
e. Flooring -  
f. Miscellaneous (cracks etc.) -  
NIL
- 6 Any major defects noticed which will render the building unsafe if any manner. -
- 7 Whether maintenance work have been done properly. - Yes
- 8 Whether the structure is sound or not for conducting classes. - The structure is sound under normal wind and weather condition.

Note:-

- 1 The suitability of the structure should be examined also with reference to location attitude intensity of wind, exposure to flood etc.
- 2 Any additional observations if deemed for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 30.05.2023 and found to be fit to conduct classes for the period 2023-24 for the reason stated above.

Place - Maranalloor

Date - 31.05.2023



Signature  
Designation  
Assistant Engineer  
LID & EW Section  
Maranalloor Grama Panchayath

31/5/2023